

FCC Verification

According to FCC Part 15

Applicant Name : SAMSUNG TECHWIN CO., LTD.

Address : #145-3, Sangdaewon 1-Dong, Jungwon-Gu,
Sunnam-Shi, Kyonggi-Do, Korea

Telephone : +82-31-740-8731

Declares that Product : Network CCD Camera

Model Name : SNP-3750N, SNP-3350N, SNP-3370N and SNP-3301N

Report Number : 2010030032

This device complies with Part 15 of the FCC rules. Operations is subject to the following two conditions: (1) This device may not cause harmful interference, and (2) This device must accept any interference received, including interference that may cause undesired operation.

Test Laboratory:

CTK Co., Ltd.

386-1, Ho-Dong, Cheoin-gu, Yongin-si, Gyunggi-do, 449-100, Korea

Designation Number : KR0025

Tel : +82-31-339-9970

Fax : +82-31-339-9855

Responsible Party:

Company Name : _____

Company Address : _____

Phone : _____

Fax : _____

Name : _____

Signature : _____



CTK Co., Ltd.
The Prime Leader of Global Regulatory Certification

CTK Co., Ltd.

386-1, Ho-dong, Cheoin-gu, Yongin-si, Gyeonggi-do, 449-100, Korea
Tel: +82-31-339-9970 Fax: +82-31-339-9855
www.e-ctk.com

EMC TEST REPORT For FCC

Test Report No. : 2010030032
Date of Issue : March 12, 2010
Model/Type No. : SNP-3750N, SNP-3350N, SNP-3370N and SNP-3301N
Kind of Product : Network CCD Camera
Applicant : SAMSUNG TECHWIN CO., LTD.
Applicant Address : #145-3, Sangdaewon 1-Dong, Jungwon-Gu, Sunnam-Shi,
Kyonggi-Do, Korea
Manufacturer : 1. SAMSUNG TECHWIN CO., LTD.
2. TIANJIN SAMSUNG TECHWIN OPTO-ELECTRONICS CO., LTD.
Manufacturer Address : 1. #42 Seongju-Dong, Changwon-Shi, Kyungsangnam-Do,
Korea
2. #No. 11 Wei Liu road Micro-electronic industrial park
Teda Tianjin China
Contact Person : Mr. Jong Min, Kang
Telephone : +82-31-740-8731
Received Date : November 5, 2009
Test period : Start : November 6, 2009 End : November 6, 2009
Test Results : ☒ In Compliance ☐ Not in Compliance

The test results presented in this report relate only to the object tested.

Tested by

Hye-Young, Lee
EMC Test Engineer
Date: March 12, 2010

Reviewed by

James Hong
EMC Technical Manager
Date: March 12, 2010