

NOTICE OF COMPLETION
AND
AUTHORIZATION TO APPLY THE UL MARK



03/02/2016

Hanwha Techwin Co Ltd
Mr. JEISOON KANG
42 Sungju-dong
Changwon-si Gyeongnam 641-716, Kr

Our Reference: File E158873, Vol. X1 Project Number 4787353507
Your Reference: KANG, JEISOON
Project Scope: USL, CNL : E158873-A102,A103,A108,A109,A110-UL / NETWORK CAMERA / SNP-6321*,
SNP-6321H*, SNP-6320RH*, SNP-5321H*, SNP-5321*
-Model name addition, SNP-L6233* for A102
-Model name addition, SNP-L6233H* for A103
-Model name addition, SNP-L6233RH* for A108
-Model name addition, SNP-L5233H* for A109
-Model name addition, SNP-L5233* for A110

Dear Mr. JEISOON KANG:

Congratulations! UL's investigation of your product(s) has been completed under the above Reference Number and the product was determined to comply with the applicable requirements. This letter temporarily supplements the UL Follow-Up Services Procedure and serves as authorization to apply the UL Mark at authorized factories under UL's Follow-Up Service Program. To provide your manufacturer(s) with the intended authorization to use the UL Mark, you must send a copy of this notice to each manufacturing location currently authorized under File E158873, Vol. X1.

Records in the Follow-Up Services Procedure covering the product are now being prepared and will be sent in the near future. Until then, this letter authorizes application of the UL Mark for 90 days from the date indicated above.

Additional requirements related to your responsibilities as the Applicant can be found in the document "Applicant responsibilities related to Early Authorizations" that can be found at the following web-site:
<http://www.ul.com/EAResponsibilities>

Any information and documentation provided to you involving UL Mark services are provided on behalf of UL LLC (UL) or any authorized licensee of UL.

We are excited you are now able to apply the UL Mark to your products and appreciate your business. Feel free to contact me or any of our Customer Service representatives if you have any questions.

Very truly yours,

Jonathan Shin
Engineer
Jonathan.Shin@ul.com

Reviewed by:

Bruce A. Mahrenholz
847-664-3009
CPO Director
Bruce.A.Mahrenholz@ul.com

CC: ,

NWTC86E-81F240